



Maricopa County

Air Quality Department

Compliance Division 1001
North Central Ave., Suite
125 Phoenix, Arizona
85004 Phone:
602-506-6010
Fax: 602-506-2163

Dear Responsible Party:

RE: Inspection Report - No Violation Noted

You are receiving this letter as a result of an inspection of your site/facility. Enclosed with this letter is your Inspection Report to notify you of the results of your inspection.

The information located on the back page of this letter will clarify the acronyms and policies referenced in the Inspection Report. Further information about the Maricopa County Air Quality Department (MCAQD) Rules and Regulations can be found at the MCAQD website: www.maricopa.gov/aq

Additional information about how you can improve air quality in Maricopa County can be found at www.CleanAirMakeMore.com

If you have any questions, you may contact the inspector noted on your Inspection Report or contact a Maricopa County Air Quality Department Compliance Supervisor, at (602) 506-6734.

Thank you,

Air Quality Compliance Division
602-506-6734

Acronyms used in the Inspection Report		
\leq – Less than or equal to	CM – Certified Mail	NTV – Non Title V
\geq – Greater than or equal to	COMS – Continuous Opacity Monitoring System	O&M Plan – Operations and Maintenance Plan
AAP – Area Accessible to the Public	DCP – Dust Control Plan	PC – Permit Condition
ACWM – Asbestos Containing Waste Material	DGO – Dust Generating Operation	RACM – Regulated Asbestos Containing Material
ASHARA – Asbestos School Hazard Abatement Reauthorization Act	ECS – Emissions Control System	RM – Regular Mail
AHERA – Asbestos Hazard Emergency Response Act	HAP – Hazardous Air Pollutant	Stab. – Stabilize
ATI – At the time of inspection	HAPRACT – Hazardous Air Pollutant Reasonable Available Control Technology	TO – Track Out
AZMACT – Arizona Maximum Achievable Control Technology	HT – Haul Truck	TOCD – Track Out Control Device
CARB – California Air Resource Board	N/A – Not Applicable	VEE – Visible Emissions Evaluation
CEMS – Continuous Emission Monitoring System	N/O – Not Observed	VOC – Volatile Organic Compound

The owner/operator is ultimately responsible for maintaining the site/facility in compliance with Maricopa County rules and regulations at all times.

INSPECTION REPORT



Maricopa County Air Quality Department
1001 N. Central Avenue, Suite 125
Phoenix, AZ 85004
Phone: (602) 506-6010 Fax: (602) 506-2537
www.maricopa.gov/aq

Date: 20-May-15
Start Time: 3:15PM End Time: 3:30PM
Inspector: Bryan Mandalfino
Phone: 602.527.5998
Email: BryanMandalfino@mail.maricopa.gov

Inspection Result:

No Violations Noted

Inspection Type: Detail inspection Office

Inspection Purpose: Reports/Plans

Permit/Notification Number:

040136

Hickman's Family Farms

6515 S. Jackrabbit Tr.

Buckeye

AZ 85326

Site Name: Hickman's Egg Ranch

Site Contact: Shari Yeatts

Site Address:

32425 W. Salome Hwy.

City:

Arlington

Phone:

623.692.8451

Inspection Rights Notification:

Not On Site

Comments

Compliance demonstration conducted on 12-May-15 to determine the average concentration of hydrogen sulfide at the nearest occupied place beyond the facility's premises

Submitted test report in compliance with the standards stated in County Rule 320: Odors and Gaseous Air Contaminants.
Average concentration of hydrogen sulfide less than 0.03 ppm by volume

Compliance Determination:
-Test Report

Delivery Method: Date: 21-May-15

Regular Mail

OFFICE USE

rec:

rev: